


Using the Bend command in 2010/2011


This White Paper will guide you through the use of the Bend command in Autodesk Inventor 2010 and 2011. The bend command will bend a part along a specified bend line within Inventor.

Intermediate Inventor and Inventor LT users

First draw a sketch on the part; this will be the bend line that the part is bent on. On the **Modify Panel drop down** choose **Bend Part**




Select the line in your sketch as the bend line. Specify the Radius and the angle.



Note that there are 3 Bend methods;

- Radius and Angle
- Radius and Arc length
- Arc Length and Angle



Selecting the Side option will bend the part on both sides