

Reference: 0101 2011 Guide by Cadline

Page 1 of 3

## elecworks™ Tips & Tricks

## **Customising the Reports**

The document template that you create new projects from not only contains the minimum set of documents you wish to start with but also the number of reports and their styles that you wish to use. Ideally if making changes to the reports, these should be done in the IEC project template so that all new projects have these new reports.

In this Tips and Tricks we will change one of the default reports in order to show how easy the reports can be manipulated and also we can add a new report into the standard set of reports produced.



Select the *Process* tab > Select

Report



Select ☑ List of Components tags



The new report list will now be shown. This information can be easily taken into marking systems such as *Weidmuller's PrintJet Pro* system


Select the List of wires by line style report from the left hand side



Select Properties













Reference: 0101 2011 Guide by Cadline

Page 2 of 3



## Select Columns tab


The columns that are already select will be shown



Right click on the area highlighted above and you will see a dropdown list of available fields

Clicking the additional fields will add or remove them from the list

Left clicking on a column and dragging it to a different position will change the order of the fields





From the Available Fields, select Wire number and then













Reference: 0101 2011
Guide by Cadline

Page 3 of 3

The field will be added into the Sort and break Condition fields changing the way the report is sorted.





14 - Bill of materials 15 - List of wires 16 - List of wires



Select Update reports drawings



